

G368

STAMPING G 368 1987
USGS QUAD MAP LAKE (1986)
NGS PID PY0945

LATITUDE 44.53860255
LONGITUDE -110.4299656
ELEVATION 2363 m

DATE OF DESCRIPTION 2002

DESCRIPTION Proceed 2.3 km (1.5 mi) southwest along the West Thumb-Lake highway from the junction of the Lake Village entrance road in Lake Village. Bench mark is near the southwest end of a large exposed area of bedrock at the top of a highway cut, 78.6 m (257.9 ft) southeast of the south corner of a restroom, 21.3 m (69.9 ft) west of the northeast end of a pullout on the east side of the road, 12.0 m (39.4 ft) northwest of the centerline of the highway, 0.9 m (3.0 ft) northwest of the southeast end of the outcrop, and about 3.0 m above the road. A paved trail passes about 7 m to the west of the bench mark

In 2002, the bench mark was found to have been damaged (chisel marks mar the face of the disk); however, the control point is recoverable and disk looks stable.



Looking east at bench mark (beneath yellow case), highway, and pullout.



Close up of bench mark.



Looking west from the pullout at the roadcut and bench mark (beneath yellow case).